

SO#	
------------	--

Other units:

CTDI Poland.

Logistyczna 7

Poland

05090 Sękocin Stary

Email: repair.emea@motorolasolutions.com Tel: +44 207 019 0461 / 0800 731 3496 Encrypted units, ASTRO/LEX11/

MXP600 devices:

Erfurter Höhe 10a

99610 Sömmerda

CTDI Germany

Germany

RMA FORM

- 1. Fields marked with * are mandatory
- 2. Please read Terms & Conditions (on the bottom of this form)
- For infrastructure and outside EU repair email the form to repair.emea@motorolasolutions.com
- Customer Care will create the RMA number for you and update the form
- Please print this form and attach to your shipment

	Attn.: Motorola Solutions Repair Attn.: Motorola Solutions Repair			
CUSTOMER INFORMATION				
Customer number *	Customer PO number			
RMA# (infrastructure, outside-EU)	Customer reference			
RETURN ADDRESS DETAILS				
Return company name *	Contact name (attn.) *			
Return full address *	Email address *			
(Street No., Apt. No., Post Code, City, Country)	Phone number			
INVOICE ADDRESS DETAILS				
Company name *	Contact name *			
Invoice full address *	Email address *			
(Street No., Apt. No., Post Code, City, Country)	Phone number			
SHIPPING INFORMATION				
Is the unit shipped in a secure box? YES NO	Security tag numbers (seals)			
UNIT INFORMATION	ecounty angular technique			
Serial number *	Unit and Fault description			
Part number / Model *				
Option (Features)				
Software version				
Software upgrade allowed YES NO				
Note: For Mototrbo Repair requiring Mainboard replacement, Firmware cannot be				
downgraded Upgrade to the latest software Return unrepaired				
Is the unit encrypted or controlled? * YES Type: NO				
End user Name and Address * (Only for ATEX, Encrypted and outside EU units)				
ACCESSORIES Battery Clip Mi	icrophone Other:			
	eadset			
FAULT INFORMATION* - Please choose at least one option				
☐ Dead ☐ Display – Error	Cannot Read / Program Battery / Charging Problem			
☐ Does not log in ☐ Physical damage	No / Low reception Constant tone			
☐ Liquid damage ☐ No / Low transmission	☐ No Signaling ☐ Chemical damage			
☐ No/ Low Audio ☐ No Squelch	Repair Code:			
SERVICE* - Please choose one option	· ·			
Warranty	Contract (or Site ID) Contract No.:			
Billed repair - with quotation	Advance exchange Contract No.:			
If quote is rejected, a fee will be charged - 60 EUR (or equivalent in your local currency)				
Billed repair - no quotation Fixed price from the official price catalogue will be charged	Scrap per Customer request			

TERMS & CONDITIONS:

- A copy of this form (with RMA number whenever applicable) is to be included with defective unit upon shipment.

 Do not send consumable items batteries, antennas, cables, SIM/ memory cards unless related to the nature of the fault.
- Please note that a 60 euro handling fee, or equivalent, might apply if a quotation is not approved within 30 days of being issued rejected, or disputed.
- Handling fees will also be charged for devices shipped to the incorrect repair location. Please be aware that warranty may be void if any unauthorised activities are detected.
- If warranty/contract is not confirmed, a quotation will be issued.
- Turn around time will be in accordance with your entitlement.

 If the software upgrade is not part of the repair then a charge may be applied.
- Most accessories are non-repairable. Faulty accessories will only be exchanged under warranty. In case warranty expired
- Faulty accessories should not be shipped to the Repair Center; exchange should be requested by completing the RMA form and emailing it to repair.emea@motorolasolutions.com.
- For Mototrbo, customer codeplug could potentially be non compatible with new (higher) FW version. In such case depot will state "Customer codeplug is not compatible with the new version FW, please reprogram the radio" in repair summary and a default codeplug will be loaded.
- For codeplug programming, if chosen by default, any return bounce unit which is related to codeplug, will not be processed as
- a bounce job.

 By submitting repairs that are deemed to be for ATEX/IECEX products, you understand and agree to have the responsibility to ensure the ATEX/IECEX repair certification documents sent out with the repaired radios are sent to the user/owner.